HP Integrity Superdome Servers

READ ME FIRST

The HP Integrity Superdome servers may require a firmware update to support Intel® Itanium® 2 Processor/Cell Add-On products shipping after June 15th, 2005.

Affected Intel® Itanium® 2 processor products for the HP Integrity Superdome are:

- AD003A Intel® Itanium® 2 1.6-GHz 9MB CPU (2-Pack)
- AD004A Instant Capacity Right To Access Intel® Itanium® 2 1.6-GHz 9MB CPU

ACTION

Check the server firmware prior to installing any of these processor products. The firmware versions can be checked using the MP "sysrev" command. The HP Integrity Superdome requires "Firmware Version rel_5.1" or later. The individual firmware revisions that make up version rel_5.1 and the firmware upgrade instructions are in the Release Notice that is included in the firmware download bundle. If you are not able to check the firmware or if the firmware is not at version rel_5.1 or later, contact HP support.

NOTE

Once the firmware is at the supported revision level, proceed with attaching the Processor/Cell Add-On Products to the server using the Service Guide. The Service Guide is available at http://docs.hp.com.

Part No.: A5201-96048